INTENSITY OF STORM/FLOOD EVENTS

BASER EN TIDE DATA	Date	Event	Inches of Rainfall	Highest Tide (ft)	Highest Plant Flow
~70yr	Feb 1978	Blizzard '78	Snow	18.42	?
	Aug 1989	Rain Storm	5.07	13.59	7 MGD
25 ~ <mark>25</mark> 47 Storem	Oct 1991	No-Name Storm	3.61	17.69 🗹	10 MGD >
20 2047-20	Dec 1992	Rain & Flood	5.54	17.52	>12.5 MGD

VETIPE FLOORS &
INCREASED PLANT FLOW

NOAA (NOAA (

Couldn't messure
peak flow

3056

7/2.5 exceeds year 2023 Utimate year Peak Daily Flow.

ORIGINAL DESIGN CALLED FOR UPSIZING INF. \$ EFF. PUMPS!

PUMPESE SISI

Appendix D

Hull WPCF

Design Data

DESIGN DATA

WATER POLLUTION CONTROL FACILITY

HULL, MASSACHUSETTS

	Corrent	Avg	Flow	N 1.7	mad)	
CENTEDAL						

I. GENERAL

Design Period Degree of Treatment Type of Treatment 25 years (1998) Secondary Conventional Activated Sludge

II. GENERAL DESIGN DATA

	Initial	Design (1998)	Ultimate (2023)
Total Population Sewered Population	10,000 4,500	31,000 26,100	37,800 37,800
Average Flow, mgd Domestic, mgd Commercial, mgd Transient, mgd Infiltration, mgd*	0.45 0.06 0.25 0.14	2.61 0.07 0.25 0.14	3.78 0.07 0.25 0.14
Total ADF, mgd Peak Daily Flow, mgd Average Septage Wastes Peak Septage Wastes	0.90 2.80 .02 .03	3.07-DESIGN 7.80 PEAK 0	4.24 -10.00 to 0
Organic Loadings Dom., Com., & Trans., lbs./day Septage Wastes, lbs./day	1520 420	5850	8200
Total, lbs/day	1940	5850	8200
Suspended Solids Dom., Com., & Trans., lbs/day Septage Wastes, lbs/da	1580 ay 500	6120	8480
Total, lbs/day	2080	6120	8480

^{*}Indicates infiltration in existing sewers after rehabilitation.
Infiltration for proposed sewers included in per capita allowance as indicated in Domestic Flow figures.

III. PRETREATMENT FACILITIES

IV.

Coarse Bar Rack Number Type Bar Spacing, inches	l Manual 2-1/2	Manual 2-1/2
Grit Removal Number Tanks Type Dimensions, feet Air Requirements, cfm/feet length Grit Screw Conveyor, Hp Blower, cfm Motor, Hp	1 Aerated 16.5x16.0x12.5 SWD 4.0-6.6 1/2 40 to 73 5	l Aerated 16.5x16.0x12.5 SWD 4.0-6.6 1/2 40 to 73 5
Fine Bar Rack (Bypass) Number Type Bar Spacing, inches	1 Manual 1-1/2	l Manual 1-1/2
Comminutors Number Capacity PDF (mgd)	11.0	11.0
*Septic Sewage Holding Tank Number Tanks Total Capacity, each, gal.	30,000	30,000
*Septic Sewage Receiving Tank Capacity	3,300	3,300
PRIMARY CLARIFIERS		
Number of Tanks Tank Diameter, feet	2 55	2 55

^{*}Septic sewage holding tank equipped with air diffusion. Septic sewage receiving tank equipped for chlorination.

4	1998	2023	
Side Water Depth, feet Surface Area, feet (Total) Overflow Rate, gpd/ft (ADF) Detention Time, hours Weir Loading Rate, gpd/lf (ADF) Overflow Rate gpd/sf (PDF)	10 4750 645 2.8 8900 1650	10 4750 900 2.0 12300 2100	
V. AERATION TANKS			
Number of Tanks Organic Loading #BOD/day Tank Dimensions (each), feet	4 4095 50x50xl2 SWD	5740 50x50x12 SWD	
Volumetric Organic Loading, #BOD/1000 cf	34	32	
Mean Biomass Loading, #BOD/lb MLSS	.35 6.9	.35 7.7	
Power Required (1.0 lb. 0 ₂ /lb BOD applied @ 3.0 lbs 0 ₂ /Hp/	14.2	20.0	
hr) Hp Power Required (for mixing @ .75 Hp/1000 ft), Hp Aerator Size, Hp	22.5 25	22.5 25	
VI. SECONDARY CLARIFIERS			
Number of Tanks Tank Diameter, feet Tank Side Water Depth, feet Surface Area (total), sf *Overflow Rate @ ADF, gpd/sf *Overflow Rate @ PDF, gpd/sf *Detention Time @ ADF, hours	2 60 12 5652 540 1380 4.0	3 60 12 8478 500 1180 4.3	
VII. POST CHLORINATION		**	
Number of Tanks Gross dimensions Net Volume (gallons) Detention Time @ PDF, min	53x31x10' SWI 88,500 16	1 + outfall 53x31x10' SWD 147,300 23.0	
*Based on Design Flow.			
**Based on utilization of 2500 feet of	of 24-inch outfa	11.	601
7 Gallong 1 Va 302 x 3 114 x 12 x 7, 48	June = TT r2	x depth x 7.48	ft3
20 83119 1 - 1111		,	¢.
253,661 gallons. = ,253 millim Sall	nn 5 ·		

V.

	1998	2023
VIII. CHLORINATORS		
Number of Machines Estimated Maximum Chlorine required lbs/day Machine Size lbs/day Chlorine Cylinder Size, tons	3 976 2 @ 500, 1 @ 50 1	3 1250 3 @ 500 1
IX. EMERGENCY POWER		500
Generator Size, kw	500	500
X. SLUDGE HANDLING		
Sludge Production Primary Sludge @ 1% Solids, lbs/day Waste Activated Sludge	3650 382 <u>0</u>	5090 5270
@ 0.5% Solids, lbs/day Total Sludge Production, lbs/day	7470	10,360
Primary - Waste Activated Sludge Blending Tank Number of Tanks Capacity, gallons Dimensions, feet Detention, min.	1 1500 5x5x8 SWD 5.1	1 1500 5x5x8 SWD 6.0
Gravity Thickeners Sludge Loading, lbs/day Number of Tanks Diameter, feet Side Water Depth Solids Loading Rate, lbs/ft ²	7470 2 30 12 5.3	10,360 2 30 12 7.3
Combined Sludge Holding Tank Solids Loading, lbs/day Number of Tanks Volume, ft Tank Dimension (each) ft Detention Time, days	7095 2 10,600 27x27x14.5 7.4	9850 2 10,600 27x27x14.5 5.3
Vacuum Filters Solids Loading, lbs/wk Number of Units Size (each) feet Solids Loading Rate, lbs/sf	49,700 2 -8ø x 6 (150ft ²) 2 4.2	$68,000$ 2 $2-80 \times 6 (150 \text{ ft}^2)$ 4.2

	1998	2023
Hrs/wk Operation Filter Cake Prod. #/hr Expected Solid Content, %	40 1263 20	55 1273 20
Sludge Incineration Total Dry Solids Loading (Sludge, Grit, Gease & Scum), lbs/wk Total Wet Solids, lbs/wk Wet Sludge Loading lbs/hr/s Ash cy/wk Incineration Size, dia. Hrs/wk Operation	22	88,390 384,200 7.2 30 x 16'-9" dia. x 7 hearth 55
MAJOR PUMPS		
Influent Pumps Type Cent Number Capacity (each), gpm Approx. Hp	. Variable Speed 4 2 @ 800, 2 @ 4,0 2 @ 20, 2 @ 50	
Effluent Pumps Type Propelle Number Capacity (each), gpm Approx. Hp	er - Var. Speed 3 2700 50	Propeller - Var. Spee 3 3500 ≡ 5. mcD 50
Recirculation Pumps Type Number Capacity, gpm Approx. Hp	Variable Speed 3 800 25	Variable Speed 3 1100 30

X.



Metcalf & Eddy Services, Inc. P.O. Box 554

Hull, Massachusetts 02045

(617) 925-0906

TO: Eric Teittinen

FROM: Ray Cranmer

DATE: November 7, 1991

SUBJECT: Emergency Incident at the Hull WWTF from 10/31/91 thru 11/4/91

Heavy rains, wind and extereme high tides on Wed 10/30/91 and Thrusday 10/31/91 caused the Treatment Plant to be inundated with salt water, sand, rocks and other debris. If not for the knowledge and dedication of John Caron and Dan Baransky the initial surge of water would have flooded the Facility. The on-site personnel (John Caron, Dan Baransky and Rich Basler) operated the pumps and hydraulic gates manually to prevent flooding the Influent and Effluent Pump room. John made a decision to send Dana Reeve and John Luniewicz home so that they could return when the tide subsided and provide much needed relief. On Thursday morning Frank Cavaleri, Pete Bernard and myself arrived at the Facility and provided much needed assistance. I can never express in words the dedication and knowledge of Frank in organizing a "Disaster Team", equipment, rentals, repairs and general supervision. I personally can never thank him enough. He is truly and "M & E Team Player".

The assistance provided by Aram Varjabedian with equipment and personnel only proves that when your in "Trouble", M & E works as a great team. Another example is John Gross who arrived here on Tuesday 11/5/91 to supervise a "Confined Space Entry" to repair a Hydraulic Gate that I believe has not worked since 1978. John not only supervised the project but also worked along side plant personnel in the Wet Well and completed the repairs to the gate within one (1) hour.

There are many people who responded and assisted without question. The list is long but I feel they all need to be recognized. Included along with yourself are:

Frank Cavaleri
John Gross
Mike Sause'
John Caron
Dan Baransky
Dana Reeve
Rich Basler
John Luniewicz
Peter Bernard

Aram Varjabedian Gary Correia Gary Murrill Greg Choukas Ed Roach Pete Nyberg Dave Doyon Mark Janson



DRAFT - ERIC - FOR YOUR REVIEW & COMMENT

MEMORANDUM

FILE: 321 DATE: September 5, 1989

TO: Wiff Peterson OFFICE: Danvers

FROM:

Frank Cavaleri

COMPANY: M&E Services

SUBJECT: HULL EMERGENCY - HULL PERSONNEL/DANVERS PERSONNEL

A series of severe events occurred at the Hull WWTP from August 11th to August 18th, 1989. The combination of these events constituted several "emergency" situations at the Hull Plant (see attached report to DEQE). Only the swift and proper response of the Hull Staff, and the assistance of the following, Norm Rogers and the Town of Hull DPW workers, Norm Lamy and Mark Janson, (Con Ops Support Maintenance Specialists), Universal Electric, (Electrical Contractor) and several other people and vendors, averted a more serious emergency. As you know, the Hull Plant has the potential of totally flooding during a major storm - and it almost did during these recent events.

The most important actions which kept the plant from totally flooding (the effluent pump room did flood to approximately 5 feet deep) was done by Dana Reeve, Maintenance Chief. Dana's quick action of shutting the influent gate and the aeration tank effluent gate and the aeration tank effluent valves, kept the effluent pump room from flooding out worse than it did. Ed Roach, Pete Wallace and Dave Dedian were also in the plant at this time, and assisted with emergency procedures.

The events that occurred over the August 11th to August 18th are too substantial to detail here. But, the seriousness of the event; the importance of the proper actions taken by the staff; the necessity (and the accomplishment) of staffing the plant for 24 hours with two people (plant staff and Con Ops Support personnel); John Caron, Assistant Plant Manager, returning early from vacation; the massive clean up when the "emergency" was under control; the assistance from Aram Varjabedian (Rockland) and Dave Doyon and Derek Baker (Fall River); and other people both within and outside M&E Services; and for all the other details that I am neglecting to mention here; all these things combined require (or I recommend) that M&E Services "corporate" recognize the dedication and hard work performed by all these people. Ed Roach did an excellent job of coordinating and managing this crisis.

We have put a substantial "commitment" into Hull, and the client and the Town are very pleased with us. Our actions during this event strengthen this commitment, and we need to reward those who deserve it, and use these events to further our goal to have a successful project.

- P.S. Eric A). I would like to discuss this memo with you, Jack & Wiff It does not say everything we need to about the events at Hull.
 - B). We need to review costs involved also.

Frank Cavaleri

FC/wjf

Rain data